

超微量工業安全實驗室 Ultra Trace Industrial Safety Hygiene

Test Report

REPORT NO: US/2013/70347

Date: 2013/08/01

Page : 1 of 2

VOLL WILL ENTERPRISE CO., LTD.

NO.186 SEC. 3 CHIEN KANG RD., TIANAN TAIWAN R.O.C.

The following sample(s) was/were submitted and identified by/on behalf of applicant as:

Sample Name: FIR-SKIN T+POLAR

Applicant: VOLL WILL ENTERPRISE CO., LTD.

Manufacturer/Vendor: VOLL WILL ENTERPRISE CO., LTD.

Country of Origin: TAIWAN

Date of Sample Received: 2013/07/25

Date of Testing: 2013/07/26

Test Results:

Test Item	CAS NO.	Test Method	Test Results	Detected Limit	Unit
Surface Resistivity		With reference to ASTM D257-93 method.	1.48E+09		Ω
		Analysis was performed by Surface			
		resistance meter.			

NOTE: 1. The report will be in vain if it is used separately.

2."N.D."non-detected means the test results is lower than detection limit value.

- END -

Signed for and on behalf

SGS Taiwan Ltd.

Anita Liao

Asst. Manager

This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司 No.38, Wu Chyuan 7th Rd., New Taipei Industrial Park, Wu Ku District, New Taipei City, 24890, Taiwan/ 新北市五股區新北產業園區五權七路38號 t+ (886-2) 2299-3939 f+ (886-2) 2298 -1338 www.tw.sgs.com



超微量工業安全實驗室 Ultra Trace Industrial Safety Hygiene

Test Report

REPORT NO: US/2013/70347

Date: 2013/08/01

/01 Page : 2 of 2

NO.186 SEC. 3 CHIEN KANG RD., TIANAN TAIWAN R.O.C.

Sample Photo



This document is issued by the Company subject to its General Conditions of Service printed overleaf, available on request or accessible at http://www.sgs.com/en/Terms-and-Conditions.aspx and, for electronic format documents, subject to Terms and Conditions for Electronic Documents at http://www.sgs.com/en/Terms-and-Conditions/Terms-e-Document.aspx. Attention is drawn to the limitation of liability, indemnification and jurisdiction issues defined therein. Any holder of this document is advised that information contained hereon reflects the Company's findings at the time of its intervention only and within the limits of Client's instructions, if any. The Company's sole responsibility is to its Client and this document does not exonerate parties to a transaction from exercising all their rights and obligations under the transaction documents. This document cannot be reproduced except in full, without prior written approval of the Company. Any unauthorized alteration, forgery or falsification of the content or appearance of this document is unlawful and offenders may be prosecuted to the fullest extent of the law. Unless otherwise stated the results shown in this test report refer only to the sample(s) tested.

SGS Taiwan Ltd. 台灣檢驗科技股份有限公司 No.38, Wu Chyuan 7th Rd., New Taipei Industrial Park, Wu Ku District, New Taipei City, 24890, Taiwan/ 新北市五股區新北產業園區五權七路38號t+ (886-2) 2299-3939 f+ (886-2) 2298-1338 www.tw.sgs.com